SIEMENS

Data sheet 6SY7000-0AD12

Spare part SIMOVERT Master drives Converter Design K Insulating washer for Pre-charging resistor 6SY7000-0AD34

Further information

Information- and Downloadcenter (Catalogs, Brochures,…)
http://www.siemens.de/industrial-controls/catalogs

Industry Mall (Online ordering system)
https://mall.industry.siemens.com

Subject to change without notice
© Copyright Siemens