

# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20160620-E33916  
**Report Reference** E33916-20061005  
**Issue Date** 2016-JUNE-20

**Issued to:** ROCKWELL AUTOMATION SWITZERLAND GMBH  
INDUSTRIESTRASSE 20  
5000 AARAU, SWITZERLAND

**This is to certify that  
representative samples of**

AUXILIARY DEVICES  
See Addendum pages for models

Have been investigated by UL in accordance with the  
Standard(s) indicated on this Certificate.

**Standard(s) for Safety:** UL 508 - Industrial Control Equipment  
CSA-C22.2 No. 14 - Industrial Control Equipment

**Additional Information:** See the UL Online Certifications Directory at  
[www.ul.com/database](http://www.ul.com/database) for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's  
Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program  
UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please  
contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



# CERTIFICATE OF COMPLIANCE

**Certificate Number** 20160620-E33916  
**Report Reference** E33916-20061005  
**Issue Date** 2016-JUNE-20

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

## Evaluated to UL 508 and CSA-C22.2 No. 14

Thermal overload relays, Models 193-KA16 or CT8-A16, 193-KA25 or CT8-A25, 193-KA40 or CT8-A40, 193-KA50 or CT8-A50, 193-KA63 or CT8-A63, 193-KA80 or CT8-A80, 193-KB10 or CT8-B10, 193-KB13 or CT8-B13, 193-KB16 or CT8-B16, 193-KB20 or CT8-B20, 193-KB25 or CT8-B25, 193-KB32 or CT8-B32, 193-KB40 or CT8-B40, 193-KB48 or CT8-B48, 193-KB63 or CT8-B63, 193-KB75 or CT8-B75, 193-KC10 or CT8-C10, 193-KC12 or CT8-C12, 193-T1AA16 or CT7N-23-A16, 193-T1AA25 or CT7N-23-A25, 193-T1AA40 or CT7N-23-A40, 193-T1AA50 or CT7N-23-A50, 193-T1AA63 or CT7N-23-A63, 193-T1AA80 or CT7N-23-A80, 193-T1AB10 or CT7N-23-B10, 193-T1AB13 or CT7N-23-B13, 193-T1AB16 or CT7N-23-B16, 193-T1AB20 or CT7N-23-B20, 193-T1AB25 or CT7N-23-B25, 193-T1AB32 or CT7N-23-B32, 193-T1AB40 or CT7N-23-B40, 193-T1AB48 or CT7N-23-B48, 193-T1AB63 or CT7N-23-B63, 193-T1AB75 or CT7N-23-B75, 193-T1AC10 or CT7N-23-C10, 193-T1AC12 or CT7N-23-C12, 193-T1AC16 or CT7N-23-C16, 193-T1AC20 or CT7N-23-C20, 193-T1AC21 or CT7N-23-C21, 193-T1AC25 or CT7N-23-C25, 193-T1BC20 or CT7N-37-C20, 193-T1BC21 or CT7N-37-C21, 193-T1BC25 or CT7N-37-C25, 193-T1BC30 or CT7N-37-C30, 193-T1BC36 or CT7N-37-C36, 193-T1BC38 or CT7N-37-C38, 193-T1CC25 or CT7N-43-C25, 193-T1CC36 or CT7N-43-C36, 193-T1CC47 or CT7N-43-C47, 193-T1DC47 or CT7N-85-C47, 193-T1DC60 or CT7N-85-C60, 193-T1DC75 or CT7N-85-C75, 193-T1DC90 or CT7N-85-C90, 193-T1DC47P or CT7N-85-C47P, 193-T1DC60P or CT7N-85-C60P, 193-T1DC75P or CT7N-85-C75P, 193-T1DC90P or CT7N-85-C90P, 193-T1CC60 or CT7N-55-C60, 193-T1DC97 or CT7N-97-C97, 193-T1DC97P or CT7N-97-C97P.

Accessory - Mounting socket, Model 193-T1APM, CT7N-37-P-A



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

