

Two speed one winding motor starter, Size 2 1/2, Three phase full voltage, solid-state overload relay OLR amp range 25-100A Enclosure type (open) No enclosure

Further information

Information- and Downloadcenter (Catalogs, Brochures,...)

<http://www.siemens.de/industrial-controls/catalogs>

Industry Mall (Online ordering system)

<https://mall.industry.siemens.com>